
OLYMPUS AUTOMATIC PROCESSING CENTER

OLYMPUS AUTOMATIC CUTTING AND MILLING CENTER WITH AUTO LOADING MAGAZINE

The CNC processing center with 9 controlled axes, is designed for cutting profiles made of PVCI. OLYMPUS loads the extruded section, machines and cuts it, then unloads the finished part all in fully automatic mode without need for operator attendance.


The powerful and versatile software can handle predefined processing lists, optimizing them to minimize wastage. The cutting head allows cutting at from 45° to 135° with the servo-controlled positioning of the head.



- min.

 the belt on the loading table allows to load
- the gripper with 2 controlled axis allows the quick positioning depending from the loaded profile.

a maximum number of 9 bars.



2. Milling side (3 controlled axis):

- milling units with 9 ELECTROSPINDLES at 24000 RPM and 1 ELECTROSPINDLE with 3 drills unit at 1400 RPM.
- The positions of the spindles are adjustable to adapt to any type of machining and profile and the high rotation speed of the tools allows maximum effectiveness in milling.
- 3 controlled axis allow the milling unit to move in X Y Z and therefore guarantee the maximum precision and speed of execution of the processes.
- X axis with a 600 mm stroke allows the cutting while milling operation to reduce at the minimum the working time.



OLYMPUS AUTOMATIC PROCESSING CENTER

3. Cutting side (2 controlled axis):

- Single-head descending miter saw with Ø550 mm blade for cuts at any angle between 45° and 135°. The downward cut allows easy unloading of the chips and swarf.
- Cutting angle positioning between 45° and 135° by means of a brushless motor and high precision gearbox with 0 play "robotic grade".
- the cutting and milling area are protected by a cabin ensuring also a noise reduction.

Cutting unit

4. Unloading side (1 controlled axis):

- The unloading carriage allows to take the piece just cut and take it outside the cutting area.
- The unloading table receives the pieces that are pushed away by the saw and, through an ejector, then makes them available to the operator.
- The unloading table with scratch-resistant strips allows to host up to 8 pieces before the operator collects them.

Unloading unit

IMPORTANT!

To ensure the maximum safety of the operator the machine must be surrounded by safety guards.

Example:

